



Replacement Fan Clutch Repair Kits for KYSOR® K26RA, K30RA and K32RA

Benefit from Horton's industry-leading customer service and quality, even if you are running its competitors' fan drives in your fleet.

- **Dual pilot for reduced inventory and complete application coverage**
- **Two-piece liner design for quick repairs**
- **Superior liner material for longer life and reliability**

Count on Horton to not only provide the reliable, durable products you need, but to deliver them on time



ENGINEERED FOR:





Rear-Air Fan Clutch

Horton # 9908504

Replaces

1090-09650-01
1090-09750-01
8801X
8801N
8905N
8901N



Rear-Air Major Kit

Horton # 9908408

Replaces

1033-40600-02
8800SKL



Rear-Air Seal Kit

Horton # 9908409

Replaces

1033-08233-01
8500SK



Lining Kit

(fit's both rear-air and front-air fan clutches)

Horton # 9908407

Replaces

1033-40600-01
8800L



Hub Bearing Kits

Horton # 9908300

Replaces

1033-07781-01
8581-01

Horton # 9908301

Replaces

1033-07782-01
8582-01

Horton # 9908302

Replaces

1033-07782-02
8582-02

Horton # 9908303

Replaces

1033-07782-03
8582-03

Horton # 9908304

Replaces

1033-07782-04
8582-04



Visit catalog.hortonww.com

to view full list of part number cross references!

Committed to Your Ideal Airflow Solution

Horton® is the premium provider of engine cooling solutions worldwide. Our culture of innovation delivers high-performance products that last and services that help you meet your commitments. Trust Horton to help your products last longer, run quieter and consume less fuel.