

CALL FOR MORE
INFORMATION



YOUR SOURCE FOR ALL THINGS DIESEL

SUPERIOR
TURBO &
INJECTION
COMPANIES

BORGWARNER COOLING SYSTEMS

K32 DuroSpeed

2-SPEED FAN DRIVE THAT RUNS COOLER TO LAST LONG



- Average 70-degree cooler running temperature.
- Innovative flux ring design dissipates heat 27% better than competing fan clutches.
- No spinning air fittings to wear out
- Easy, Inexpensive conversion of On/Off clutches using our flux ring assembly fit.
- 11 fewer components
- 5 to 10 lbs weight savings versus competitive 2-speed drives

Kysor ON/OFF




- Proven and robust: Most durable bearing package and base design for commercial vehicle line haul duty cycle.
- Line haul clutch of choice: 30% less power consumption
- Simple: 20% fewer components
- Ease of maintenance: Liner is serviceable on the truck
- Modular design: Just the clutch can be replaced for easy, low cost service.
- All makes clutch: One part number minimizes inventory & costs.

Visctronic



- Precise fan speed control: ECU closed loop control optimizes fan speed for improved fuel economy and horsepower availability.
- Quiet fan operation: Smooth fully variable control reduces noise and vibration for reduced drive fatigue and improved cooling system durability.
- Low parasitic drag at fan idle speed
- Maintenance free: Self contained unit, nothing to service or maintain.
- Proven, reliable technology: Invented by Borgwarner, in production for decade.

Bi-Metal Viscous



- Simple and effective variable drive: Bi-metallic sensor modules fan speed allowing for smooth and efficient operation.
- Stand-Alone control: Simple bimetallic sensor requires no system interface.
- Maintenance free: Self-contained unit, nothing to service or maintain.
- Smooth, soft engagements: for extended belt and accessory life.
- Proven, reliable and cost-effective technology.

**LOCATIONS
SERVING YOU**

Detroit Superior Turbo & Injection. 3745 Central Street | Detroit, MI 48210 | (313) 842-4616

Grand Rapids Diesel Injection Service. 430 54th St SW | Grand Rapids, MI 49548 | (616) 531-1030

Edwardsburg Stateline Diesel Service. 25162 US Highway 12E | Edwardsburg, MI 49112 | (269) 663-8571

Blissfield Superior Turbo & Injection. 211 N Jipson St | Blissfield, MI 49228 | (517) 486-0000

FAN DRIVE CROSS REFERENCE

Description	Part #	Cross Reference
Drive Assembly 750 Viscous	10020755	166054, 166283, 167341, 167524, 169683, 9802005, 9802012, 9902005, 9902012, 9902014, 10020755, 1210-09157-01, 2001023C1, 2021954C1, 2027495C1, 2029206C1, 2601975C1, 3522788C2, 3522788C3, 3522788C91, RV0210900-00
	10020791	167071, 167421, 167981, 9802004, 9802007, 9902007, 10020791, 1210-09156-02, 2022686C1, 2033827C1, 2038840C1, 2601973C1, 3540983C1, 3540983C2, 3540983C3, RV0311100-00
	10020914	167046, 9802004, 9802013, 9803002, 9902004, 9902013, 9903002, 1210-09155-01, 2004860C1, 2021376C1, 2601974C1, 3522786C1, 3522786C2, 3522786C3, RV0210900-00
	10021314	167118, 167120, 167122, 167332, 169366, 199807, 199809, 199810, 199811, 199812, 10021314, 1689479C1, 1689480C1, 1689481C1, 1689481C2, 1689482C1, 1689936C1, 1690060C1, 2027494C1, 2602037C91, RV0410200-00
	10021288	3609117C2, RV0710400-03
Drive Assembly 805 Viscous	10021526	9802013, 9902013, 3584438C1, 010019556, 3584438C2, 3584438C3, RV0610400-03
	10021530	9802015, 9902015, 12100916803, 3540116C1, 3540116C2, 3540116C3, 3540116C4, 4C4Z-8A616-AB, YB625, RV0610500-00
Hub Bearing Kit	1033-07781-01	9908300, 1695793C91, 8581-01
	1033-07782-01	9908301, 858201, 1696090C91, 8582-01
K32/K30/K26 Steel Liner Kit	1033-40600-01	9908407, 10330934001, 8800L, 1090-09650-01, 1090-09600-01, 1090-09500-01
K32/K30/K26 Steel Service Kit	1033-40600-02	85134490, 9908405, 2509688C91, 10330933901, 85112571, 10334060002, 8800SKL, 1090-09650-01, 1090-09600-01, 1090-09500-01
Fan Clutch Assembly K26FA	1090-09000-01	2156290, 3081867, 15734989, 0104-FF4, 1617899C91, 20822-3486, 40MH52, E8HZ-8A616-A, F3HZ-8A616-C, OB080020, 8001X
	1090-09000-05A	25155636, 65140704, 85123181, 85129485, 1080-08000-05, 1090-07050-03, 1090-08000-05A, 40MH33, 8005X
Fan Clutch K32RA 2.9/16 Steel	1090-09650-01	450533, 10900965001, 1090-09500-01, 1090-09500-01B, 1090-09650-01, 1090-09650-01B, 2514343C91, 3403415013, 3403915592, 490F8HZ8A627UA, 6552501022C91, 6552509380C91, 6552601022C91, 6552602141C91, 85134489, 87585111808, 87585114233, 87585134489, 8801N, 8801X
Fan Clutch K32RA 5.0" Steel	1090-09750-01	1090-09900-01, 1090-09900-01B, 1090-09950-01, 1090-09950-01B, 8801N
Visctronic Drive for Prostar Horton Stratis Replacement*	010025195P	9806014, 9906014, 9806017, 9906017, 9906051, 3625107C95, 3856801C91, 3893209C91, 3893209C92, 01002882B
XD11 Fan for Prostar Horton Stratis Replacement*	F10026097P	

*Fan must be ordered with Visctronic if you do not already have XD11 fan